# X-TREMA LOCK SPLICE PROCEDURE FOR PHILLYSTRAN ROPES: 12-Strand HMPE Braids

MATERIALS NEEDED: Scissors, Marker, Two colors of electrical tape

## **STEP ONE – SETTING UP FOR THE SPLICE:**

- A. Measure out the tail length.
- B. Length of tail = 44 x bare diameter.
- C. Mark the tail length by wrapping electrical tape tightly around it.
- D. Measure out the eye length.
  - The eye should be at least (30 x bare diameter) for HMPE braids.
  - Measure this length from the tail mark away from the end of the rope.



- E. Separate the tail
  - Separate the tail all the way up to the tail mark.
  - There should be 12 individual strands.
  - Tape all of the LHL one color (black).
  - Tape all of the RHL another color (white).
- F. Group the tails
  - Combine the 12 individual strands into 6 groups of 2 strands.
  - They should be grouped by twist direction.





151 Commerce Drive Montgomeryville, PA 18936-9628 USA Phone: 215-368-6611 Fax: 215-362-7956 Web: <u>www.phillystran.com</u> E-mail: <u>information@phillystran.com</u> Page 1 of 3



#### **STEP TWO – STARTING THE SPLICE**

- A. Insert 2 groups of RHL and 1 group of LHL strands directly through the middle of the braid at the second mark (the mark for the eye) and pull snug to form the eye.
- B. Tuck each group under a single body-strand that is braided in the same direction as the individual strands are twisted (LHL group under LHL strand in body).
- C. Once each of the 6 groups is tucked under one strand each then the "startup" of the splice is complete.







#### **STEP THREE – SPLICING THE BRAID**

(Note: The following steps are directionally moving directly away from the eye marks)

- A. Select the center-most group (the group closest to where the two eye-marks meet).
  - Separate the group into two individual strands.
  - One of them is to go over the body-strand directly next to it then under the next.
  - The second individual strand is to go under the third body-strand
  - This constitutes one individual tuck.
  - Repeat this step until five individual tucks have been completed.

151 Commerce Drive Montgomeryville, PA 18936-9628 USA Phone: 215-368-6611 Fax: 215-362-7956 Web: <u>www.phillystran.com</u> E-mail: <u>information@phillystran.com</u> Page 2 of 3



### STEP THREE - SPLICING THE BRAID (cont.)

- B. Taper the two individual strands
  - After the first five individual tucks, carefully cut out 1/3 of each of the two strands.
  - Make sure to leave at least the length of 1 lay length sticking out of the rope.
- C. Complete three more individual tucks.
- D. Taper again (remove an additional 1/3 of the strands).
- E. Complete three more individual tucks.When this is complete, then you are 1/6 of the way through step three.
- F. Repeat all of step three for each of the 5 remaining strands.

#### WRAP UP

- A. The all of the tails left outside of the splice must be at least 1 lay length long.
- B. When the splice is first loaded, they will "suck in" to the splice.
- C. The finished splice should be protected in some manner.



**CAUTION: Break Strength:** The breaking strength of a rope is the load at which a new rope will break when tested under laboratory conditions. Break strength should not be mistaken for safe working load. **Safe Working Load:** Because of the wide range of rope use, rope condition and the degree of risk of life or property, it is not possible to make a blanket recommendation for safe working load. It is ultimately dependent on the rope user to determine what percentage of break strength is their own safe working load. **Wear:** Ropes wear out with use; the more severe the usage, the greater the wear. It is often not possible to detect wear on a rope by visible signs alone. Therefore, it is recommended that the rope user determine a retirement criteria for ropes in their application. For assistance in developing safe working load and retirement criteria for each application please call or write Phillystran.

All printed statements, data and recommendations are based on reliable information and tests, and are presented without any guarantee or warranty. Statements regarding the use of Phillystran's products and processes are not to be construed as recommendations for use in violation of any applicable laws, regulations or patent rights. © All rights reserved.

151 Commerce Drive Montgomeryville, PA 18936-9628 USA Phone: 215-368-6611 Fax: 215-362-7956 Web: <u>www.phillystran.com</u> E-mail: <u>information@phillystran.com</u> Page 3 of 3



A WireCo<sup>®</sup> WorldGroup Brand



